## CERTIFICATE FITNESS

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

				2	P .
-				1	1
3	Α,	1	-	1/	
		-04	14	1	
			1	/	-
		1	1		

vame of the Officer

Nature of defects, if any a) Foundation and basement

c) Doors and Windows

b) Superstructure

e) Roof

fi Flooring

Name of the School

Location with name of Education District/ Sub. District

Crassification of Building as specified in column 4 of the application for fitness certificate and size.

Er. Sumesb. V.M Fr. Thomas Pourkara (entral school champal

kuttanad Mancomb Pennenant building Deound floor

1. 6.54x7.00 x 3.60 -1 nos

2. 6.54× 7.05× 3.60 -1 No

3. 6.44 x 6.5 4x 3.66- 1 No

Stark case 6.54 x 3.1 - 1 No 4. 1.44 x 6.5 0x 3.60 . 1 00

5.7.42 x 6.50 x 3.60 - 1 No

Period for which the certificate is issued - 2024 - 25

6.7.42 x 6.50 x 3.60 -1 No

7. b.36 x 6.52 x 3. 60 - 1 No

first floor 1. 6. 54x7.00 x3.6 - 1 No

2. 6.54×7.00×3.6 - 1 No

3. 6.44 x 6.54 x 3.6-1 No

Staria 6.54x3.1

4-7.44 x 6.56 x 3.6- 1 No

stais . 6.87 x 6.50 6.36x3.1

5. 7.42x6.5x3.6 - 1 No

6. 7.43 x 6.5 x 3 6 - 1 No

constructed bobe regularised 7.6.36x6.5x3.6-1 No

Any major defects noticed which will render the 8. 6.36×7.1×3.6-1 No building unsafe in any manner

New building already

d) Wood work wrought and put up

Whether maintenance works have been done properly

Yes

Whether the structure is sound or not for conducting classes

Sound under no emal weather condition

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind. exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on

Nil

23/05/2024

and

found to be fit / unfit to conduct, classes, for the period .....

2024-25

reasons stated above

I ace Man Comby

[ ate: 23/05/2024





