

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
 (Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

Name of the Officer

Name of the School

Location with name of Education District/ Sub. District

Classification of Building as specified in column 4 of the application for fitness certificate and size.

Period for which the certificate is issued 2024 - 25

Nature of defects, if any

a) Foundation and basement

b) Superstructure

c) Doors and Windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks, etc.)

Any major defects noticed which will render the building unsafe in any manner

Nil

New building already constructed to be regularised for its fitness.

*Eg. Suresh V. M  
 Fr. Thomas Porukara Central School Champakulam  
 Kuttanad Mancomb  
 Permanent building  
 ground floor*

1.  $6.54 \times 7.00 \times 3.60$  - 1 no  
 2.  $6.54 \times 7.05 \times 3.60$  - 1 no  
 3.  $6.44 \times 6.54 \times 3.60$  - 1 no  
 staircase  $6.54 \times 3.1$  - 1 no  
 4.  $7.44 \times 6.50 \times 3.60$  - 1 no  
 5.  $7.42 \times 6.50 \times 3.60$  - 1 no  
 6.  $7.42 \times 6.50 \times 3.60$  - 1 no  
 7.  $6.36 \times 6.52 \times 3.60$  - 1 no  
 first floor 1.  $6.54 \times 7.00 \times 3.6$  - 1 no  
 2.  $6.54 \times 7.00 \times 3.6$  - 1 no  
 3.  $6.44 \times 6.54 \times 3.6$  - 1 no  
 stairs  $6.54 \times 3.1$   
 4.  $7.44 \times 6.56 \times 3.6$  - 1 no  
 stairs  $6.87 \times 6.50$  -  $6.36 \times 3.6$   
 5.  $7.42 \times 6.5 \times 3.6$  - 1 no  
 6.  $7.43 \times 6.5 \times 3.6$  - 1 no  
 7.  $6.36 \times 6.5 \times 3.6$  - 1 no  
 8.  $6.36 \times 7.1 \times 3.6$  - 1 no

Whether maintenance works have been done properly

Yes

Whether the structure is sound or not for conducting classes

sound under normal weather condit

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on

23/05/2024

found to be fit / unfit to conduct classes for the period


2024 - 25

Reasons stated above

I ace: Mancomb

Date: 23/05/2024

*SL*  
**MANAGER**  
**FR. THOMAS PORUKARA CENTRAL SCHOOL**  
**CHAMPAKULAM P.O., ALAPPUZHA**



*SB*  
**ASSISTANT ENGINEER**  
**FR. SUBIN KOTTOOR CMI**  
**PRINCIPAL**  
**FR. THOMAS PORUKARA CENTRAL SCHOOL**  
**CHAMPAKULAM P.O., ALAPPUZHA, KERALA**

*23/05/2024*

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
 (Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

Name of the Officer

Name of the School

Location with name of Education District/ Sub. District

Classification of Building as specified in column 4 of the application for fitness certificate and size.

Period for which the certificate is issued 2024 - 25

Nature of defects, if any

a) Foundation and basement

b) Superstructure

c) Doors and Windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks, etc.)

Any major defects noticed which will render the building unsafe in any manner

Nil

New building already constructed to be regularised for its fitness.

*Fir. Suresh V. M  
 Fr. Thomas Porukara Central school Champakulam  
 Kuttanad Mancomb  
 Permanent building  
 ground floor*

1.  $6.54 \times 7.00 \times 3.60$  - 1 no  
 2.  $6.54 \times 7.05 \times 3.60$  - 1 no  
 3.  $6.44 \times 6.54 \times 3.60$  - 1 no  
 staircase  $6.54 \times 3.1$  - 1 no  
 4.  $7.44 \times 6.50 \times 3.60$  - 1 no  
 5.  $7.42 \times 6.50 \times 3.60$  - 1 no  
 6.  $7.42 \times 6.50 \times 3.60$  - 1 no  
 7.  $6.36 \times 6.52 \times 3.60$  - 1 no  
 first floor 1.  $6.54 \times 7.00 \times 3.6$  - 1 no  
 2.  $6.54 \times 7.00 \times 3.6$  - 1 no  
 3.  $6.44 \times 6.54 \times 3.6$  - 1 no  
 stairs  $6.54 \times 3.1$   
 4.  $7.44 \times 6.56 \times 3.6$  - 1 no  
 stairs  $6.87 \times 6.50$  -  $6.36 \times 3.6$   
 5.  $7.42 \times 6.5 \times 3.6$  - 1 no  
 6.  $7.43 \times 6.5 \times 3.6$  - 1 no  
 7.  $6.36 \times 6.5 \times 3.6$  - 1 no  
 8.  $6.36 \times 7.1 \times 3.6$  - 1 no

Whether maintenance works have been done properly

Yes

Whether the structure is sound or not for conducting classes

sound under normal weather condit

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on

23/05/2024

found to be fit / unfit to conduct classes for the period

2024 - 25

Reasons stated above

I ace: Mancomb

Date: 23/05/2024

*SL*  
**MANAGER**  
**FR. THOMAS PORUKARA CENTRAL SCHOOL**  
**CHAMPAKULAM P.O., ALAPPUZHA**



*SB*  
**ASSISTANT ENGINEER**  
**FR. SUBIN KOTTOOR CMI**  
**PRINCIPAL**  
**FR. THOMAS PORUKARA CENTRAL SCHOOL**  
**CHAMPAKULAM P.O., ALAPPUZHA, KERALA**

*23/05/2024*